



Chittagong Dry Dock Limited

Bangladesh Navy
East Patenga, Chattogram, Bangladesh

Mobile: +8801769744971
E-mail: bnmtwcddl@gmail.com, Website: www.cddl.gov.bd



23.02.1565.341.53.003.25.56

Dated: 22 September 2025

INVITATION FOR OPEN TENDER

1.	Procuring Entity Name	Chittagong Dry Dock Ltd.
2.	Invitation for	Purchase of MT Spare Parts
3.	Invitation Reference No	-
4.	Procuring Method	Open Tender.
5.	Budget & Source of Funds	Own Fund of BN MT Workshop.
6.	Tender Selling Date (Office Time only)	23 September 2025 to 08 October 2025 at 12.00 PM
7.	Tender Closing Date and Time	09 October 2025 at 12.15 PM
8.	Tender Opening Date & Time	09 October 2025 at 12.30 PM
9.	Name and Address of the Office(s) for Selling, Receiving and Opening of Tender Documents:	(1) Cash Section, Accounts Department, Chittagong Dry Dock Ltd, Bangladesh Navy, East Patenga, Chattogram. (2) Schedule will also be available at CDDL's website.
	a. Selling Tender Document	
	b. Receiving Tender Document	Production Department, Chittagong Dry Dock Ltd.
	c. Opening Tender Document	(1) Chittagong Dry Dock Ltd, Bangladesh Navy, East Patenga, Chattogram. (2) Tenderers and their authorized representatives are allowed to attend.
10.	Price of Tender Document	TK 500.00 (Five Hundred) (Non-refundable)
11.	Contact Details	Mobile: +8801769744971, +8801769744972 E-mail: bnmtwcddl@gmail.com
12.	Special Instructions	a) The procuring entity reserves the right to reject all or any tenders prior to acceptance without showing any reason. b) Suppliers may submit quotations for all spare parts or for spare parts related to one or more types of vehicles. c) Partial quotation is also allowed. d) Detail technical specifications are mentioned in schedule.

SYED SHAFIQUUL ISLAM
Lt Cdr BN
OIC



TENDER SPECIFICATION OF MT SPARE PARTS
BN MT WORKSHOP



Ser	Particular	Description	
1.	Name of Item	MT Spare Parts	
2.	Description of Vehicles	Brand and Model of Vehicles	Quantity of Parts
		a. Toyota Land Cruiser Jeep Chassis No: JTEFB71J008003739 Model No: HZJ71R-RJMRS	555
		b. Toyota Hiace Chassis No: JTFJK02P500029283 Model No: LH202R-REMDE	57
		c. Toyota Land Cruiser V8 Chassis No: JTMHX05J104173440 Model No: URJ202R-GNTEKQ	16
		d. Mitsubishi Montero Chassis No: JMYLNV96WGJ000235 Model No: V96WLNFR	108
		e. Mitsubishi Lancer EX Chassis No: JMYSRCY1AFU000756 Model No: CY1ASRSHR	63
		f. Mitsubishi Lancer GLX Chassis No: JMYSRCS1ADU000271 Model No: CS1ASRJER	140
		g. Mitsubishi L-200 Chassis No: MMBJNKL30GH040298 Model No: KL3T	210
3.	Quantity of Parts (Total)	1149	
4.	Number or Types of Parts	77 (Seventy Seven) Line	
5.	Purpose	The items will be used to repair and maintenance of vehicle	
6.	Country of Origin (Main Equipment)	Japan	
7.	Country of Manufacture	Japan/Thailand/Indonesia/Malaysia/Taiwan (Each line items manufacturing country to be mentioned)	
8.	Year of Manufacture	2024 or later	
9.	Source of Supply	To be mentioned	
10.	Port of Shipment	To be mentioned	
11.	Manufacturer's Name and Address	To be mentioned	
12.	Supplier/ Local Agent	To be mentioned	
13.	Certificate and Document of Authentication	An authentication certificate complying all items are genuine & new is to be provided by supplier.	
14.	Packaging/ labeling	Items need to be packed well & safe condition	
15.	Acceptance	Acceptance will be given after satisfactory quality inspection & completion of mustering all spare parts	
16.	Terms of Payment	a) 95% on completion of acceptance of all spare parts. b) 5% within 6 (six) months from the date of acceptance.	

SYED SHAFIQUUL ISLAM
Lt Cdr BN
OIC

Toyota Land Cruiser - Jeep

Chassis: JTEFB71J008003739

Model Number: HZJ71R-RJMRS

Total Vehicle: 85

SL NO	DISCRIPTION OF SPARE PARTS	PART NO	Unit	Requirement Qty	Per Unit Rate	Total Price	Remarks
1	Knuckle Kit	43204-60032	Set	60			
2	King pin bearing	90366-20003	Pcs	24			
3	Wheel hubs bearing big	90080-36064	Pcs	20			
4	Wheel hub's oil seal	90311-62001	Pcs	40			
5	Wheel hubs bearing small	90080-36067	Pcs	20			
6	Drive shaft oil seal	90310-36003	Pcs	40			
7	A/C fan belt	99332-11260	Pcs	10			
8	Stabilizer bar bush	48815-60040	Pcs	20			
9	Link rod	48802-60050	Pcs	10			
10	End sub assy, steering relay rod L/H	45045-69075	Pcs	20			
11	End sub assy, steering relay rod R/H	45044-69135	Pcs	20			
12	Tie rod end sub assy R/H	45047-69085	Pcs	20			
13	Tie rod end sub assy L/H	45046-69135	Pcs	20			
14	Leaf spring bush	90385-18021	Pcs	150			
15	Back light L/H side	81561-90K09	Pcs	11			
16	Brake master cylinder	47201-60831	Pcs	5			
17	Clutch master cylinder	31470-60290	Pcs	5			
18	Propeller shaft cross bearing (Rear)	04371-36050	Pcs	10			
19	Propeller shaft cross bearing (Front)	04371-60070	Pcs	10			
20	Front LH Side Door Outer Handle	69220-90K00	Pcs	40			

Toyota Hiace
Model Number : LH202R-REMDE
Chassis No: JTFJK02P500029283

Total Vehicle: 26

SL NO	DISCRIPTION OF SPARE PARTS	PART NO	Unit	Requirement Qty	Per Unit Rate	Total Price	Remarks
1	Rear brake shoe	04495-26240	Pcs	7			
2	Clutch disc assy	31250-26222	Pcs	10			
3	Clutch cover assy	31210-26164	Pcs	10			
4	A/C filter	87139-26010	Pcs	10			
5	Stabilizer link rod complete L/H	48820-26051, 90948-02193, 48817-26020, 90948-02005	Set	5			
6	Stabilizer link rod complete R/H	48820-26051, 90948-02193, 48817-26020, 90948-02005	Set	5			
7	Belt, V (Cooler,compressor to crank shaft pulley)	99332-61170	Pcs	5			
8	Belt, V (For vane pump)	99332-00920	Pcs	5			

Toyota Land Cruiser V8
MODEL NUMBER: URJ202R-GNTEKQ
Chassis No: JTMHX05J104173440

Total Vehicle: 02

SL NO	DISCRIPTION OF SPARE PARTS	PART NO	Unit	Requirement Qty	Per Unit Rate	Total Price	Remarks
1	A/C filter	87139-50100	Pcs	4			
2	Engine oil filter	04152-38020	Pcs	4			
3	Front brake pad	04465-60280	Set	4			
4	Rear brake pad	04466-60160	Set	4			

Mitsubishi Montero
Model Number: V96WLNFR

Chassis No: JMYLNV96WGJ000235

Total Vehicle: 11

SL NO	DISCRIPTION OF SPARE PARTS	PART NO	Unit	Requirement Qty	Per Unit Rate	Total Price	Remarks
1	Engine oil filter	ME013307	Pcs	10			
2	Fan belt	MH014570	Pcs	10			

Mitsubishi Lancer EX
Model Number: CY1ASRSHR
Chassis No: JMYSRCY1AFU000756 **Total Vehicle: 16**

SL NO	DISCRIPTION OF SPARE PARTS	PART NO	Unit	Requirement Qty	Per Unit Rate	Total Price	Remarks
1	Spark plug	1822A086	Pcs	20			
2	Front shock absorber R/H side	4060A378	Pcs	13			
3	A/C filter	7803A004	Pcs	10			
4	C.V joint	3815A454	Pcs	10			
5	Inner joint boot cover	3815A224	Pcs	10			

Mitsubishi Lancer GLX
Model Number: CS1ASRJER
Chassis No: JMYSRCS1ADU000271 **Total Vehicle: 21**

SL NO	DISCRIPTION OF SPARE PARTS	PART NO	Unit	Requirement Qty	Per Unit Rate	Total Price	Remarks
1	Ignition coil wire	MD365102	Pcs	10			
2	Rear shock absorber	MR519613	Pcs	10			
3	A/C filter	7803A103	Pcs	20			
4	Oil filter	MD365876	Pcs	20			
5	Tie rod end	4422A054	Pcs	10			
6	Rack end	4422A078	Pcs	10			
7	Spark plug	MD350292	Pcs	40			
8	Stabilizer link rod	4056A161	Pcs	10			
9	Stabilizer bush	MR491192	Pcs	10			

Mitsubishi L-200**Model Number: KL3T****Chassis No: MMBJNKL30GH040298****Total Vehicle: 09**

SL NO	DISCRIPTION OF SPARE PARTS	PART NO	Unit	Requirement Qty	Per Unit Rate	Total Price	Remarks
1	Release bearing	MR195689	Pcs	20			
2	Brake shoe	4600A106	Set	5			
3	Clutch plate	2301A117	Pcs	20			
4	AC filter	7803A112	Pcs	10			
5	Engine oil filter	1230A186	Pcs	10			
6	Pressure plate	2304A010	Pcs	20			
7	Pilot bearing	MD335444	Pcs	10			
8	Front shock absorber	4062A101	Pcs	10			
9	Tie rod end LH	4422A096	Pcs	5			
10	Tie rod end RH	4422A097	Pcs	5			
11	Rack end	4410A173	Pcs	10			
12	Stabilizer bar bush	4056A219	Pcs	10			
13	Stabilizer link rod LH	4056A198	Pcs	5			
14	Stabilizer link rod RH	4056A199	Pcs	5			
15	Steering rack boot	4410A759	Pcs	10			
16	Rear shock absorber	4162A289	Pcs	10			
17	Leaf spring bush	MB584531	Pcs	40			
18	Timing belt Big	1145A081	Pcs	5			